



| | | | | | |
|---|---|---|---|------|-----|
| C | A | S | B | 0709 | V01 |
|---|---|---|---|------|-----|



Date : 29th December 2023

ANNEXURE - I

| Rule No. | Sub Rule(s) | Compliance Verified For | | Standard | |
|----------|---|--|--------------------------|---------------------------------|-------------------------------|
| 93 | (1)(A), (1)(B) & 2 | Motor vehicle width, length and height | | - | |
| 94 | (1), (2) & (3) | Condition of tyres | | - | |
| 95 | (1), (2), (3), (4), (5) & (6) (Tubeless) | Size & ply rating of tyres | | IS 15627:2005 & AIS-050:2004 | |
| | | Front | 90/100-10, 53J | | M/s MAXXIS M/s CEAT |
| | | | Rear | | 90/100-10, 53J |
| | | | 110/90-10, 61J | | M/s MAXXIS |
| 96 | (1), (2), (3),(4)(ib), (7)(c) & (8) | Brakes | | IS 14664:2010 | |
| 102 | (1), (2) & (3) | Signaling devices, direction indicators and stop lights | | - | |
| 103 | (1) | Position of the indicator | | - | |
| 104 | (1) & (4) | Fitment of reflectors | | AIS-057 (Rev. 1): 2010 | |
| 105 | (1)(bb), (2)(i) & (4) | Lamps | | - | |
| 106 | (1) | Deflection of lights | | - | |
| 108 | (1) | Use of red or white lights | | - | |
| 111 | - | Prohibition of spotlights etc. | | - | |
| 117 | (1) & (2) | Speedometer | | IS 11827:2008 | |
| 119 | (1) & (2) | Horns | Installation (Below 7kW) | | IS 15796:2008 |
| | | | Limit : | 83 dB(A) to 112 dB(A) | |
| | | | Observed : | 87 dB(A) | |
| | | Performance | | IS 1884:1993 | |
| 120 | (2) | Pass by Noise | Limit : | 75 dB(A) | IS 3028:1998 |
| | | | Observed : | 58 dB(A) | |
| 122 | (1) & (2) | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) | | AIS-065:2005 | |
| 123 | (1) | Safety devices in motor cycle | Pillion Handhold | | IS 14495:1998 |
| | (2) | | Footrests | | AIS 148:2018 |
| | (4) | | Stand | | AIS 146:2018 |
| | (5) | | External Projection | | AIS 147:2018 |
| 124 | Refer Annexure-IA & IB | Safety standards of components as applicable | | - | |
| 125 | (2)(a) | Rear View | Specifications | | AIS-001 (Part 2) (Rev.1):2011 |
| | | Mirror | Installation | | AIS-002 (Part 2) (Rev.1):2011 |

| | |
|-----------------------|------------------------------|
| ICAT Ref No. | 2023-1224 (IOCS Ref: 170492) |
| Power Test Report No. | CT0PS 0754 Dt. 22.06.2023 |
| Noise Report No. | CT0VS 1179 dt. 21.07.2023 |
| Horn Inst. Report No. | CT0VR 0607 dt. 29.04.2022 |

AUTHORISED SIGNATORY

| | | |
|---|--|----------------|
|  VIKAS SADAN DEPUTY GENERAL MANAGER |  SAURABH DALELA DIRECTOR | Page 2 of 4 |
|---|--|----------------|