







C A P N 0091 F01 V02

ANNEXURE - I

Date : 10th January 2024

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1) & (2)	Overall dimension of motor vehicles		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2),(3), (4), (5), (6) (Cross Ply & with tube)	Size & ply rating of tyres		IS:15636-2005 & AIS:051 - 2004 AIS 142	
		Front	235/75 R 17.5 14 PR (Single)		M/s JK Tyres and Industries Ltd.
		Rear	235/75 R 17.5 14 PR (Dual)		M/s JK Tyres and Industries Ltd.
96	(1), (2),(3),(4)(ii), (7)(a),(8)	Brakes with ABS		IS:11852 - 2013	
98	(1), (2), (3)	Steering Gear		IS:11948 -2010	
				IS:12222 - 2011	
99	-	Forward and backward motion		-	
100	(1), (2), (3) & (3c)	Safety glass		IS 2553 (Part 2) (Revision 1): 2019	
101	(1) & (2)	Windscreen wiper		IS 15802:2008	
102	(1) & (2)	Signalling devices, direction indicators and stop lights		-	
103	(1) & (2)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS:057 (Rev. 1)- 2010	
105	(1) (a), (2), (3), (4) & (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking light		-	
111	-	Prohibition of spotlights etc.		-	
114	(1) & (2)	Exhaust gases and exhaust pipes		-	
115	(1), (2)(ii) & 18(ii)	Emission of smoke, vapour, etc. from motor vehicle (Including OBD II)		AIS-137 Part 4	
117	(1) & (2)	Speedometer		IS:11827-2008	
118	(1) & (2)	Speed Governor (ECU - M/s Bosch India Ltd., ID- 0281036684)		AIS:018 - 2001	

ICAT Ref No.	2023-1308 (IOCS Ref: 170678)
Engine Test Report No.	CT0ER 0424 dt. 02.11.2022, CT0ER 0424 E01 dt. 18.06.2023 & CT0ER 0425 dt. 02.11.2022 (OBD II)
Noise Report No.	CT0VP0165 dt. 13.12.2020, CT1VR1425 dt. 14.10.2022 & CT1VR1425 C01 dt. 22.11.2022
Horn Inst. Report No.	CT0VO0772 dt. 13.08.2019

AUTHORISED SIGNATORY				
	VIKAS SADAN DEPUTY GENERAL MANAGER			