



C A T B 0115





Date : 05<sup>th</sup> February 2024

ANNEXURE - I

| Rule No. | Sub Rule(s)                              | Compliance Verified For  |                          | Standard                      |                       |
|----------|--|--|--------------------------|-------------------------------|-----------------------|
| 93       | (1)(A), 1(B), 2                          | Motor vehicle width, length and height   |                          | -                             |                       |
| 94       | (1), (2) & (3)                           | Condition of tyres   |                          | -                             |                       |
| 95       | (1), (2), (3), (4), (5) & (6) (Tubeless) | Size & ply rating of tyres   |                          | IS 15627:2005 & AIS-050:2004  |                       |
|          |  | Make   | TVS Tyre                 |                               |                       |
| 96       | (1), (2), (3), (4)(ib), (7)(c) & (8)     | Front / Rear   | 90/90-12,54J             | TVS Tyre                      |                       |
|          |  |  | 90/90-12,54J             |                               |                       |
| 96       | (1), (2), (3), (4)(ib), (7)(c) & (8)     | Brakes with CBS  |                          | IS 14664:2010                 |                       |
| 102      | (1), (2) & (3)                           | Signaling devices, direction indicators and stop lights  |                          | -                             |                       |
| 103      | (1)                                      | Position of the indicator  |                          | -                             |                       |
| 104      | (1) & (4)                                | Fitment of reflectors  |                          | AIS-057 (Rev. 1): 2010        |                       |
| 105      | (1)(bb), (2)(i) & (4)                    | Lamps  |                          | -                             |                       |
| 106      | (1)                                      | Deflection of lights   |                          | -                             |                       |
| 108      | (1)                                      | Use of red or white lights   |                          | -                             |                       |
| 111      | -  | Prohibition of spotlights etc.   |                          | -                             |                       |
| 117      | (1) & (2)                                | Speedometer  |                          | IS 11827:2008                 |                       |
| 119      | (1) & (2)                                | Horns  | Installation (Below 7kW) | IS 15796:2008                 |                       |
|          |  |  | Limit :                  |                               | 83 dB(A) to 112 dB(A) |
|          |  |  | Observed :               |                               | 85.7 dB(A)            |
|          |  |  | Performance              |                               | IS 1884:1993          |
| 120      | (2)                                      | Pass by Noise  | Limit :                  | 75 dB(A)                      |                       |
|          |  |  | Observed :               | 58 dB(A)                      |                       |
| 122      | (1) & (2)                                | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) |                          | AIS-065:2005                  |                       |
| 123      | (1), (2), (4), (5)                       | Safety devices in motor cycle  | Pillion Handhold         | IS 14495:1998                 |                       |
|          |  |  | Footrests                | AIS 148:2018                  |                       |
|          |  |  | Stand                    | AIS 146:2018                  |                       |
|          |  |  | External Projection      | AIS 147:2018                  |                       |
| 124      | Refer Annexure-IA & IB                   | Safety standards of components as applicable   |                          | -                             |                       |
| 125      | (2)(a)                                   | Rear View  | Specifications           | AIS-001 (Part 2) (Rev.1):2011 |                       |
|          |  | Mirror   | Installation             | AIS-002 (Part 2) (Rev.1):2011 |                       |

|                       |                              |
|-----------------------|------------------------------|
| ICAT Ref No.          | 2023-0715 (IOCS Ref: 168536) |
| Power Test Report No. | CTOPS 0978 dt. 28.09.2023    |
| Noise Report No.      | CTOVS 1473 dt. 01.09.2023    |
| Horn Inst. Report No. | CTOVS 1865 dt. 21.11.2023    |

**AUTHORISED SIGNATORY**

|   |   |   |  |
|---|---|---|--|
| <br><b>JAYWANT HARDIKAR</b><br>HEAD-CMVR |  | <br><b>SAURABH DALELA</b><br>DIRECTOR | <br>Page 2 of 4 |
|---|---|---|--|