



C A T B 0139





Date : 08<sup>th</sup> February 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B) & 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Front	3.00-10, 42J	IS 15627:2005 & AIS-050:2004	
		Rear	3.00-10, 42J		
96	(1), (2), (3),(4)(ib), (7)(c) & (8)	Brakes		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Below 7kW)	IS 15796:2008	
			Limit :		87 dB(A) to 112 dB(A)
			Observed :		95.9 dB(A)
120	(2)	Pass by Noise	Limit :	75 dB(A)	
			Observed :	59 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Safety devices in motor cycle	Pillion Handhold	IS 14495:1998	
	(2)		Footrests	AIS 148:2018	
	(4)		Stand	AIS 146:2018	
	(5)		External Projection	AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part 2) (Rev.1):2011	
		Mirror	Installation	AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2023-0809 (IOCS Ref: 168875)
Power Test Report No.	CTOER 0311 dt. 29.07.2022
Noise Report No.	CT0VT 0081 dt. 23.01.2024
Horn Inst. Report No.	CT0VT 0086 dt. 23.01.2024

**AUTHORISED SIGNATORY**

 <b>JAYWANT HARDIKAR</b> HEAD-CMVR		 <b>SAURABH DALELA</b> DIRECTOR	 Page 2 of 4
---	---	---	--