



C A T B 0139





Date : 08<sup>th</sup> February 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard		
93	(1)(A), (1)(B) & 2	Motor vehicle width, length and height		-		
94	(1), (2) & (3)	Condition of tyres		-		
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004		
		Front	3.00-10, 42J		M/s TVS M/s RALSON M/s CEAT	
		Rear	3.00-10, 42J	M/s TVS M/s RALSON M/s CEAT		
96	(1), (2), (3),(4)(ib), (7)(c) & (8)	Brakes		IS 14664:2010		
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-		
103	(1)	Position of the indicator		-		
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010		
105	(1)(bb), (2)(i) & (4)	Lamps		-		
106	(1)	Deflection of lights		-		
108	(1)	Use of red or white lights		-		
111	-	Prohibition of spotlights etc.		-		
117	(1) & (2)	Speedometer		IS 11827:2008		
119	(1) & (2)	Horns	Installation (Below 7kW)		IS 15796:2008	
			Limit :	87 dB(A) to 112 dB(A)		
			Observed :	95.9 dB(A)		
			Performance		IS 1884:1993	
120	(2)	Pass by Noise	Limit :	75 dB(A)		IS 3028:1998
			Observed :	59 dB(A)		
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005		
123	(1)	Safety devices in motor cycle		Pillion Handhold	IS 14495:1998	
	(2)			Footrests	AIS 148:2018	
	(4)			Stand	AIS 146:2018	
	(5)			External Projection	AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-		
125	(2)(a)	Rear View	Specifications		AIS-001 (Part 2) (Rev.1):2011	
		Mirror	Installation		AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2023-0809 (IOCS Ref: 168875)
Power Test Report No.	CTOER 0311 dt. 29.07.2022
Noise Report No.	CT0VT 0081 dt. 23.01.2024
Horn Inst. Report No.	CT0VT 0086 dt. 23.01.2024

**AUTHORISED SIGNATORY**

 <b>JAYWANT HARDIKAR</b> HEAD-CMVR		 <b>SAURABH DALELA</b> DIRECTOR	 Page 2 of 4
---	---	---	--