



C	A	L	B	0011	F02
---	---	---	---	------	-----

Date : 15<sup>th</sup> February 2024

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Front/ Rear	Size & ply rating of tyres	Make
			90/90-12, 54L	RALSON
		3.75-12 66E	APOLLO	
		90/90-12 54J	MRF	
		3.75-12 60J	JK TYRE	
		90/90-12 54J	POWERMIX	
		3.75-12 60J	TVS	
3.75-12 66B	PODDAR			
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1), (2), (3)	Safety glass		NA
101	(1)	Windscreen Wiper		NA
102	(1), (2)	Signaling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119	(1) & (2)	Horns	Installation	IS 15796:2008 Amd.3:2019
			Limit : 83 dB(A) to 112 dB(A)	
			Observed : 93.0 dB(A) / 94.1 dB(A)	
			Performance	IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View Mirror	Specifications	AIS-001 (Part-2)Rev.1:2011
			Installation	AIS-002 (Part-2)Rev.1:2011

ICAT Ref No.	2023-0628 (168213)
Power Test Report No.	CT0ES 0368 Dt.04.08.2023 & CT0PS 1046 Dt.07.11.2023
Horn Inst. Report No.	CT0CK 4247 dt. 23.12.2015 & CT1VS 2026 Dt.26.12.2023

**AUTHORISED SIGNATORY**




**JAYWANT HARDIKAR**  
HEAD-CMVR

**SAURBH DALELA**  
DIRECTOR