



C	A	L	B	0084	F03
---	---	---	---	------	-----

Date : 23<sup>rd</sup> February 2024

**ANNEXURE - I**

Rule No.	Sub Rule(s)	Compliance Verified For	Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height	-	
94	(1), (2), (3)	Condition of tyres	-	
95	(1), (2), (3), (4), (5) & (6) (Front/ Rear) TT-Tube type TL-Tube less	Size & ply rating of tyres	Make	
		90/90-12, 64B(TT) / 3.75-12, 67B (TT)	CEAT	
		90/90-12 54J (TL) / 3.75-12, 60J (TT)	TVS	
		3.75-12, 66B (TT), 90/90-12, 54L (TL)	Ralson	
		3.75-12, 66E (TT) / 90/90-12, 64B (TT)	JK Tyre	
		3.75-12, 66E (TT)	MRF	
		3.75-12, 66E (TT)	Apollo	
		3.75-12, 66B (TT)	Poddar	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes	IS 14664:1999	
99	-	Forward and backward motion	-	
100	(1), (2), (3)	Safety glass	NA	
101	(1)	Windscreen Wiper	NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights	-	
103	(1), (2)	Position of the indicator	-	
104	(1)(v), (4)	Fitment of reflectors & reflective tapes	AIS-057(Rev.1):2010 & AIS090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps	-	
106	(1)	Deflection of lights	-	
108	(1)	Use of red or white lights	-	
109	-	Parking lights	-	
110	-	Lamps for three wheelers	-	
111	-	Prohibition of spotlights etc.	-	
119	(1) & (2)	Installation	IS 15796:2008	
		Limit :		83 dB(A) to 112 dB(A)
		Observed :		94.9 dB(A)
		Performance	IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)	AIS-065-2005	
124	-	Safety standards of components as applicable	Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View	Specifications	
		Mirror	Installation	
			AIS-001 (Part-2) Rev.1:2011	
			AIS-002 (Part-2) Rev.1:2011	

ICAT Ref No.	2023-1008; (169286)
Power Test Report No.	CT0PS 1092 dt. 19.12.2023
Horn Inst. Report No.	CTOLL-0383 dt. 11.04.2016

<b>AUTHORISED SIGNATORY</b>			
<b>JAYWANT HARDIKAR</b> HEAD-CMVR		<b>SAURBH DALELA</b> DIRECTOR	Page 2 of 3