




C A T B 0331


Date : 28th March 2024



ANNEXURE - I


Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6)	Size & ply rating of tyres		 IS 15627:2005 & AIS-050-2004	
		Front/ Rear	3.75X12,66J (Tube Type)		Braza
			3.75x12-66B (Tube less and Tube type)		Ralson
		Front/ Rear	3.75x12-60J (Tube Type) & 90x90-12-54J(Tube less)		TVS
			3.75-12-66B(Tube Type)		CEAT
3.75-12-66E(Tube Type)	Metro				
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1), (2), (3)	Safety glass		NA	
101	(1)	Windscreen Wiper		NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1), (2)	Position of the indicator		-	
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Installation		IS 15796:2008	
		Limit :	83 dB(A) to 112 dB(A)		
		Observed :	104.5 dB(A)		
		Performance		IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part-2)Rev.1:2011	
		Mirror	Installation	AIS-002 (Part-2)Rev.1:2011	

ICAT Ref No. 2022-2327; (IOCS: 165444)
 Power Test Report No. CTOPS 0641 dt. 02.05.2023
 Horn Inst. Report No. CT0VS 0882 dt. 31.05.202³

AUTHORISED SIGNATORY


JAYWANT HARDIKAR
 HEAD - CMVR



SAURABH DALELA
 DIRECTOR


 Page 2 of 3