



C	A	L	B	0193	F01
---	---	---	---	------	-----

Date : 29th March 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004	
		Front/ Rear	90/90-12 54L(Tube less), 3.00-12 63B(Tube type & Tube less) & 3.75-12 66B(Tube type & Tube less)		RALSON
			3.75-12 66E (Tube Type)		APOLLO TYRE
			90/90-12,64B & 3.75-12, 66B (Tube Type)		CEAT
			90/90-12, 54J Tube less & 3.75 x 12, 60J (Tube Type)		TVS
3.75-12, 66E (Tube Type)	JK Tyre Ind. Ltd.				
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1),(2),(3)	Safety glass		NA	
101	(1)	Windscreen Wiper		NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights		NA	
103	(1), (2)	Position of the indicator		-	
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS-090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Horns	Installation	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		102.0 / 93.5 dB(A)
			Performance	IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref. Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part-1)Rev.1:2011	
		Mirror	Installation	AIS-002 (Part-1)Rev.1:2011	

ICAT Ref No.	2023 -1380 (IOCS: 171227)
Power Test Report No.	CT0ES 0038 Dt.25.01.2023 &CT0PS 0390 Dt.07.03.2023
Horn Inst. Report No.	CT0CK 2789 dt. 25.08.2015 &CT1VS 2071 Dt.30.12.2023

AUTHORISED SIGNATORY

JAYWANT HARDIKAR HEAD -CMVR	MANESAR	SAURBH DALELA DIRECTOR	Page 2 of 3