



C A T B 0461

Date : 07th May 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-	
94	(1), (2), (3)	Condition of tyres		-	
95	(1), (2),(3), (4), (5) & (6) (Tube Type)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004	
		Front/ Rear	3.75-12 72B 6PR		RALSON
			90/90-12,64B & 3.75-12, 66B		CEAT Limited
			3.75-12.66E		Apollo
			3.75-12 66E & 90/90-12 64B		MRF Limited
			3.75-12 66E & 90/90-12 64B		JK Tyre Ind. Ltd.
			90/90-12 54J & 3.75-12 60J		TVS Srichakra Ltd
3.75-12 60J & 90/90-12 54J	Powermax				
		3.75-12, 66B	Poddar Tyres		
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999	
99	-	Forward and backward motion		-	
100	(1), (2), (3)	Safety glass		NA	
101	(1)	Windscreen Wiper		NA	
102	(1), (2)	Signaling devices, direction indicators and stop lights		-	
103	(1), (2)	Position of the indicator		-	
104	(1)(v),(4)	Fitment of reflectors & reflective tapes		AIS-057(Rev.1):2010 & AIS090-2005	
105	(1)(b), (3), (4), (5), (7)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
109	-	Parking lights		-	
110	-	Lamps for three wheelers		-	
111	-	Prohibition of spotlights etc.		-	
119	(1) & (2)	Installation		IS 15796:2008	
		Limit :	83 dB(A) to 112 dB(A)		
		Observed :	95.1 dB(A)		
		Performance		IS 1884:1993	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005	
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part-2)Rev.1:2011	
		Mirror	Installation	AIS-002 (Part-2)Rev.1:2011	

ICAT Ref No.	2023-2414 (172020)
Power Test Report No.	CT0PS 0796 Dt.06.07.2023
Horn Inst. Report No.	CT0VS 1701 Dt.21.10.2023

AUTHORISED SIGNATORY			
JAYWANT HARDIKAR HEAD- CMVR		SAURBH DALELA DIRECTOR	Page 2 of 3