







C A T B 0501

Date : 22nd May 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5) & (6) (Tube Type)	Front/ Rear	Size & ply rating of tyres	Make
			3.75-12 66B, 4PR	CEAT
		3.75-12 66B, 6PR	RALSON	
		3.75-12, 60J, 4PR	TVS	
		3.75-12, 66E, 4PR	MRF	
96	(1), (2), (3), (4)(i), (7)(b)	Brakes		IS 14664:1999
99	-	Forward and backward motion		-
100	(1), (2), (3-A) & (3)(c)	Safety glass		NA
101	(1)	Windscreen Wiper		-
102	(1), (2)	Signaling devices, direction indicators and stop lights		-
103	(1), (2)	Position of the indicator		-
104	(1)(v), (4)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005
105	(1)(b), (3), (4), (5), (7)	Lamps		-
106	(1)	Deflection of lights		-
108	(1)	Use of red or white lights		-
109	-	Parking lights		-
110	-	Lamps for three wheelers		-
111	-	Prohibition of spotlights etc.		-
119	(1) & (2)	Horns	Installation	
			Limit :	83 dB(A) to 112 dB(A)
			Observed :	98.9 dB(A)
		Performance		IS 15796:2008
				IS 1884:1993
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
124	-	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View	Specifications	AIS-001 (Part-2)Rev.1:2011
		Mirror	Installation	AIS-002 (Part-2)Rev.1:2011

ICAT Ref No.	2023- 1972 (IOCS No. 173053)
Power Test Report No.	CT0VT0380 Dt.06.05.2024 & CT0ER 0499 Dt.08.12.2022
Horn Inst. Report No.	CT0VT 0641 Dt.22.04.2024

AUTHORISED SIGNATORY				
	JAYWANT HARDIKAR HEAD-CMVR			