







C	A	R	B	0078	F01	V02
---	---	---	---	------	-----	-----

Date : 30th August 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A), 1(B), 2	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front/Rear	Make		
		90/90-12, 54L	M/s RALCO		
		90/90-12, 54J	M/s CEAT M/s TVS		
96	(1), (2), (3), (4)(ib), (7)(c) & (8)	Brakes with CBS		IS 14664:2010	
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Horns	Installation (Below 7kW)	IS 15796:2008	
			Limit :		83 dB(A) to 112 dB(A)
			Observed :		85.7 dB(A)
			Performance	IS 1884:1993	
120	(2)	Pass by Noise	Limit :	75 dB(A)	
			Observed	58 dB(A)	
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1)	Safety devices in motor cycle	Pillion Handhold	IS 14495:1998	
	(2)		Footrests	AIS 148:2018	
	(4)		Stand	AIS 146:2018	
	(5)		External Projection	AIS 147:2018	
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part 2) (Rev.1):2011	
		Mirror	Installation	AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2023-2367 (IOCS Ref: 174657)
Power Test Report No.	CTOES 0224 dt. 19.04.2023
Noise Report No.	CT0VQ 1515 dt. 21.12.2021, CT0VR 0588 dt. 25.04.2022
Horn Inst. Report No.	CT0VQ 1516 dt. 21.12.2021, CT1VS 1028 dt. 21.06.2023 & CT0VT 0835 dt. 14.05.2024

AUTHORISED SIGNATORY				
	JAYWANT HARDIKAR HEAD-CMVR			