



C A T B 0910


Date : 01st October 2024

ANNEXURE - I


Rule No.	Sub Rule(s)	Compliance Verified For		Standard	
93	(1)(A) & (1)(B)	Motor vehicle width, length and height		-	
94	(1), (2) & (3)	Condition of tyres		-	
95	(1), (2), (3), (4), (5) & (6) (Tubeless)	Size & ply rating of tyres		IS 15627:2005 & AIS-050:2004	
		Front/Rear	90/80-17 46P/ 110/80-17 57P		M/s MRF
96	(1), (2), (3), (4)(ib), (4)(A), (7)(c) & (8)	Brakes with ABS		IS 14664:2010	
		Front/Rear	90/80-17 46H/ 110/80-17 57P		M/s JK Tyre (Cavendish)
102	(1), (2) & (3)	Signaling devices, direction indicators and stop lights		-	
103	(1)	Position of the indicator		-	
104	(1) & (4)	Fitment of reflectors		AIS-057 (Rev. 1): 2010	
105	(1)(bb), (2)(i) & (4)	Lamps		-	
106	(1)	Deflection of lights		-	
108	(1)	Use of red or white lights		-	
111	-	Prohibition of spotlights etc.		-	
117	(1) & (2)	Speedometer		IS 11827:2008	
119	(1) & (2)	Installation (Below 7kW)		IS 15796:2008	
		Limit :	83 dB(A) to 112 dB(A)		
		Observed :	86.4 dB(A)		
		Performance			IS 1884:1993
120	(2)	Pass by Noise		IS 3028:1998	
		Limit :	75 dB(A)		
122	(1) & (2)	Observed :		IS 3028:1998	
		63 dB(A)			
122	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065:2005	
123	(1), (2), (4), (5)	Safety devices in motor cycle		Pillion Handhold	IS 14495:1998
				Footrests	AIS 148:2018
				Stand	AIS 146:2018
				External Projection	AIS 147:2018
124	Refer Annexure-IA & IB	Safety standards of components as applicable		-	
125	(2)(a)	Rear View	Specifications	AIS-001 (Part 2) (Rev.1):2011	
		Mirror	Installation	AIS-002 (Part 2) (Rev.1):2011	

ICAT Ref No.	2024-0669 (IOCS Ref: 178348)
Power Test Report No.	CTOET 0351 dt. 06.09.2024
Noise Report No.	CTOVT 1561 dt. 30.09.2024
Horn Inst. Report No.	ARA/SHL/CT/APX-2021-2024


AUTHORISED SIGNATORY



JAYWANT HARDIKAR
HEAD-CMVR



SAURABH DALELA
DIRECTOR



Page 2 of 4