



C A T B 0916

Date : 07th October 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5) & (6)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004
		Front/Rear	Make	
96	(1), (2), (3), (4)(i), (7)(b)	Refer Annexure - IV		IS 14664:1999
99	-	Brakes		-
100	(1), (2), (3-A) & (3)(c)	Forward and backward motion		-
101	(1)	Safety glass		IS 2553 (Part 2)(Rev 1):2019
102	(1)	Windscreen Wiper		-
103	(1), (2)	Signaling devices, direction indicators and stop lights		-
104	(1)(v),(4)	Position of the indicator		-
105	(1)(b), (3), (4), (5), (7)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005
106	(1)	Lamps		-
108	(1)	Deflection of lights		-
109	(1)	Use of red or white lights		-
110	-	Parking lights		-
111	-	Lamps for three wheelers		-
119	(1) & (2)	Horns	Installation	IS 15796:2008
			Limit : 83 dB(A) to 112 dB(A)	
			Observed : 100.8 dB(A)	
122	(1) & (2)	Performance		IS 1884:1993
124	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
125	(2)(a)	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
		Rear View Mirror	Specifications	AIS-001 (Part-2)Rev.1:2011
			Installation	AIS-002 (Part-2)Rev.1:2011

ICAT Ref No. 2024-0477 (IOCS: 177706)
 Power Test Report No. CT0ET 0163 Dt.12.04.2024 & CT0PT 0546 Dt.30.07.2024
 Horn Inst. Report No. CT0VT 1410 Dt.13.09.2024

AUTHORISED SIGNATORY

JAYWANT HARDIKAR HEAD-CMVR		SAURBH DALELA DIRECTOR	Page 2 of 4