



C A T B 0927

Date : 09<sup>th</sup> October 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5) & (6)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004
		Front/ Rear	Make	
96	(1), (2), (3), (4)(i), (7)(b)	Refer Annexure - IV		IS 14664:1999
99	-	Brakes		-
100	(1), (2), (3-A) & (3)(c)	Forward and backward motion		-
101	(1)	Safety glass		NA
102	(1)	Windscreen Wiper		-
103	(1), (2)	Signaling devices, direction indicators and stop lights		-
104	(1)(v), (4)	Position of the indicator		-
105	(1)(b), (3), (4), (5), (7)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005
106	(1)	Lamps		-
108	(1)	Deflection of lights		-
109	(1)	Use of red or white lights		-
110	-	Parking lights		-
111	-	Lamps for three wheelers		-
119	(1) & (2)	Horns	Installation	IS 15796:2008
			Limit : 83 dB(A) to 112 dB(A)	
			Observed : 96.2 dB(A)	
122	(1) & (2)	Performance		IS 1884:1993
124	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
125	(2)(a)	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
		Rear View Mirror	Specifications	AIS-001 (Part-2) Rev.1:2011
			Installation	AIS-002 (Part-2) Rev.1:2011

ICAT Ref No.	2023-2081 (IOCS No. 173963)
Power Test Report No.	CT0PR 0826 dt. 29.06.2022
Horn Inst. Report No.	CT0VR 1690 dt. 30.11.2022

<b>AUTHORISED SIGNATORY</b>			
<b>JAYWANT HARDIKAR</b> HEAD-CMVR		<b>SAURBH DALELA</b> DIRECTOR	Page 2 of 4