



C A T B 0997

Date : 05<sup>th</sup> November 2024

ANNEXURE - I

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1)(A), (1)(B), (2)	Motor vehicle width, length and height		-
94	(1), (2), (3)	Condition of tyres		-
95	(1), (2), (3), (4), (5), & (6)	Size & ply rating of tyres		IS 15627:2005 & AIS-050-2004
		Front/ Rear	Make	
96	(1), (2), (3), (4)(i), (7)(b)	Refer Annexure - IV		IS 14664:1999
99	-	Brakes		-
100	(1), (2), (3-A) & (3)(c)	Forward and backward motion		-
101	(1)	Safety glass		NA
102	(1)	Windscreen Wiper		NA
103	(1), (2)	Signaling devices, direction indicators and stop lights		-
104	(1)(v),(4)	Position of the indicator		-
105	(1)(b), (3), (4), (5), (7)	Fitment of reflectors & reflective tapes		AIS-057-2005 & AIS-090-2005
106	(1)	Lamps		-
108	(1)	Deflection of lights		-
109	(1)	Use of red or white lights		-
110	-	Parking lights		-
111	-	Lamps for three wheelers		-
119	(1) & (2)	Horns	Installation	IS 15796:2008
Limit :			83 dB(A) to 112 dB(A)	
Observed :			91.9 dB(A)	
122	(1) & (2)	Performance		IS 1884:1993
124	(1) & (2)	Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications)		AIS-065-2005
125	(2)(a)	Safety standards of components as applicable		Refer ANNEXURE - IA & IB
125	(2)(a)	Rear View	Specifications	AIS-001 (Part-2)Rev.1:2011
		Mirror	Installation	AIS-002 (Part-2)Rev.1:2011

ICAT Ref No. 2024-0319 (IOCS: 176828)  
 Power Test Report No. CT0ES 0414 Dt.24.08.2023 & CT0PT 0127 Dt.17.01.2024  
 Horn Inst. Report No. CT0VT 0366 Dt.04.03.2024

**AUTHORISED SIGNATORY**

JAYWANT HARDIKAR HEAD-CMVR		SAURBH DALELA DIRECTOR	Page 2 of 4