



|   |   |   |   |      |     |
|---|---|---|---|------|-----|
| C | A | T | B | 0866 | V03 |
|---|---|---|---|------|-----|

Date : 23<sup>rd</sup> December 2024

**ANNEXURE - I**

| Rule No. | Sub Rule(s)                                 | Compliance Verified For  |                          | Standard                     |                               |
|----------|---|--|--------------------------|------------------------------|-------------------------------|
| 93       | (1)(A), (1)(B) & 2                          | Motor vehicle width, length and height   |                          | -                            |                               |
| 94       | (1), (2) & (3)                              | Condition of tyres   |                          | -                            |                               |
| 95       | (1), (2), (3), (4), (5) & (6)<br>(Tubeless) | Front  | 90/90-12, 54J            | IS 15627:2005 & AIS-050:2004 |                               |
|          |   | Rear   |                          |                              | M/s Ceat                      |
| 96       | (1), (2), (3), (4)(ib), (7)(c) & (8)        | Brakes   |                          | IS:14664:2010                |                               |
| 102      | (1), (2) & (3)                              | Signaling devices, direction indicators and stop lights  |                          | -                            |                               |
| 103      | (1)   | Position of the indicator  |                          | -                            |                               |
| 104      | (1) & (4)                                   | Fitment of reflectors  |                          | AIS-057 (Rev. 1): 2010       |                               |
| 105      | (1)(bb), (2)(i) & (4)                       | Lamps  |                          | -                            |                               |
| 106      | (1)   | Deflection of lights   |                          | -                            |                               |
| 108      | (1)   | Use of red or white lights   |                          | -                            |                               |
| 111      | -   | Prohibition of spotlights etc.   |                          | -                            |                               |
| 117      | (1) & (2)                                   | Speedometer  |                          | IS 11827:2008                |                               |
| 119      | (1) & (2)                                   | Horns  | Installation (Below 7kW) |                              | IS 15796:2008                 |
|          |   |  | Limit :                  | 83 dB(A) to 112 dB(A)        |                               |
|          |   |  | Observed :               | 89.1 dB(A)                   |                               |
|          |   |  | Performance              |                              | IS 1884:1993                  |
| 120      | (2)   | Pass by Noise  | Limit :                  | 75 dB(A)                     | IS 3028:1998                  |
|          |   |  | Observed :               | 60 dB(A)                     |                               |
| 122      | (1) & (2)                                   | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) |                          | AIS-065:2005                 |                               |
| 123      | (1)   | Safety devices in motor cycle  | Pillion Handhold         |                              | IS 14495:1998                 |
|          | (2)   |  | Footrests                |                              | AIS 148:2018                  |
|          | (4)   |  | Stand                    |                              | AIS 146:2018                  |
|          | (5)   |  | External Projection      |                              | AIS 147:2018                  |
| 124      | Refer Annexure-IA & IB                      | Safety standards of components as applicable   |                          | -                            |                               |
| 125      | (2)(a)                                      | Rear View  | Specifications           |                              | AIS-001 (Part 2) (Rev.1):2011 |
|          |   | Mirror   | Installation             |                              | AIS-002 (Part 2) (Rev.1):2011 |

|                              |                             |
|------------------------------|-----------------------------|
| <b>ICAT Ref No.</b>          | 2024-0303; IOCS Ref: 180421 |
| <b>Power Test Report No.</b> | CTOET 0335 Dt. 29.08.2024   |
| <b>Noise Report No.</b>      | CT1VT 1547 Dt. 30.09.2024   |
| <b>Horn Inst. Report No.</b> | CT1VT 1717 Dt. 06.11.2024   |

|                             |                                      |                                   |  |  |             |
|-----------------------------|--------------------------------------|-----------------------------------|--|--|-------------|
| <b>AUTHORISED SIGNATORY</b> |                                      |                                   |  |  |             |
|                             | <b>JAYWANT HARDIKAR</b><br>HEAD-CMVR | <b>SAURABH DALELA</b><br>DIRECTOR |  |  |             |
|                             |                                      |                                   |  |  | Page 2 of 4 |