



C A U B 0183

Date : 20th February 2025

ANNEXURE - I

| Rule No. | Sub Rule(s) | Compliance Verified For | | Standard |
|-----------------|-------------------------------|--|---|--|
| 93 | (1)(A), (1)(B), (2) | Motor vehicle width, length and height | | - |
| 94 | (1), (2), (3) | Condition of tyres | | - |
| 95 | (1), (2),(3), (4), (5) & (6) | Size & ply rating of tyres | Make | IS 15627:2005 & AIS-050-2004 |
| | Front/ Rear | Refer Annexure - IV | | |
| 96 | (1), (2), (3), (4)(i), (7)(b) | Brakes | | IS 14664:1999 |
| 99 | - | Forward and backward motion | | - |
| 100 | (1), (2), (3-A) & (3)(c) | Safety glass | | NA |
| 101 | (1) | Windscreen Wiper | | - |
| 102 | (1), (2) | Signaling devices, direction indicators and stop lights | | - |
| 103 | (1), (2) | Position of the indicator | | - |
| 104 | (1)(v),(4) | Fitment of reflectors & reflective tapes | | AIS-057-2005 & AIS-090-2005 |
| 105 | (1)(b), (3), (4), (5), (7) | Lamps | | - |
| 106 | (1) | Deflection of lights | | - |
| 108 | (1) | Use of red or white lights | | - |
| 109 | - | Parking lights | | - |
| 110 | - | Lamps for three wheelers | | - |
| 111 | - | Prohibition of spotlights etc. | | - |
| 119 | (1) & (2) | Horns | Installation Limit : 83 dB(A) to 112 dB(A) Observed : 102.5 dB(A) | IS 15796:2008 |
| | | | Performance | IS 1884:1993 |
| 122 | (1) & (2) | Embossment of chassis number & motor number & month of manufacture (Ref: Table 11 of the Technical Specifications) | | AIS-065-2005 |
| 124 | | Safety standards of components as applicable | | Refer ANNEXURE - IA & IB |
| 125 | (2)(a) | Rear View Mirror | Specifications Installation | AIS-001 (Part-2)Rev.1:2011 AIS-002 (Part-2)Rev.1:2011 |

| | |
|------------------------------|---|
| ICAT Ref No. | 2024-2565 (IOCS No.175382) |
| Power Test Report No. | CT0ER 0536 dt.31.12.2022 & CT0PT 0681 dt 10.10.2024 |
| Horn Inst. Report No. | CTOVS 1919 dt. 06.12.2023 |

AUTHORISED SIGNATORY

JAYWANT HARDIKAR
HEAD-CMVR



SAURABH DALELA
DIRECTOR

