



[A Division of National Automotive Board (NAB), Govt. of India]

Report No. ICAT/DT/JBM/25-26/U-0076

Date : 04th April 2025

Report No.
ICAT/DT/JBM/25-26/U-0076

PMP VERIFICATION / ASSESSMENT REPORT



1	Name of applicant/OEM	M/s JBM Auto Limited
2	Plant Address	M/s JBM Electric Vehicles Pvt. Ltd. 81 km Milestone, Delhi-Agra Highway NH 2, Village- Banchari, Hodel, Palwal, Haryana- 121106
3	OEM's Reference	C&H/12-2024/005, Dt. 05.12.2024
4	Docket ID & Date	CDJBMATNFAM182481, Dt. 06.12.2024
5	a) Vehicle Model	ECOLIFE E9 LF
	b) Vehicle Category	M3
	c) Chassis No.	M2701B2408LB01911
	d) Motor Model No.	LSM170C-HV2200-A2
	e) Vehicle Segment as per FAME-II Guidelines	e-Bus (Battery Electric Vehicle)
6	CMVR Certificate Reference	CATB 0358, Dt. 30.03.2024
7	Objective	To Conduct PMP Verification/Assessment of Parts [specified in Table 1 of CESL Tender NIT/Bid Document No. CESL/06/2022-23/e buses/GC-2/222309007 dated 22.09.2022(E-Tender Id-1897)] of e-Bus Mentioned in Sr.No 5 above as per FAME-II Guidelines as requested by the applicant/OEM.
8	Observations/PMP Assessment	The PMP compliance of PMP Parts were verified as per FAME-II and ICAT's approved Guidelines/Process. For detailed observations/PMP Assessments, please refer Annexure-I .

Note:- The evaluation/verification other than PMP verification as per FAME-II guidelines is not part of this PMP verification/Assessment Report

		IOCS No.- 182481			
Prepared By		Checked by		Approved By	
					
LOKESH SAINI		AMIT KARWAL		SAURABH DALELA	
Engineer		Dy. General Manager		Director	
					
				Page 1 of 10	

Please turn for disclaimer