

TAC/Reference No. CN 2

Date : 01st November 2022

Cert Dwg Total 02 pgs

	Customer's Name	M/s. BMW India Private Limited
2 5. Bhi	Customer's Address	2nd Floor, Oberoi Centre, Building No. 11, DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India
3 3	Manufacturing / Assembly Plant Address	M/s. Prime Wheel Exportadores 115 Canon del Padre, 22203 Tijuana, Mexico
ited Wo	0023 Me. Eta	Type of Wheel Rim Aluminium Alloy Wheel Rim for Passeng Cars-Normal Highway Service
inite	Cry 30/3 me. p. Burkling . Stinger I'm	Size of Wheel Rim
Private	Description of the Test Component(s)	Part No. 6883522
4 Rida Pil	Description of the rest Component(s), and the standard st	7 1/2JX18H2 IS25 GREY 21 362 2 BMW 6883522 MADE IN MEXICO 006043/20 >AISi7< PRIME TJ
Ms. Buy	h kida zinat as Litited C AxXX and	Applicable Vehicle Model
5	Applicable Notified Standard	IS: 9436 -2018 with Amend. No.1, February 2021
6 420.1	Test Report No.	CT0CR2022 dated 01.11.2022
6.1	List of supporting documents	Drawing No. 6 883 522
Sil I Co	Pre-test inspection Visit Report No.	Not Applicable Not Applicable Stripe Life
8	Details of Quality Management System (QMS)	Not Applicable
11.09 11.09	Approval	Granted/ Not Granted/ Extended
10	The CoP period for the component mentione shall be completed before 30.09.2024.	d in Sr. No. 4 above shall begin from the date of production & 1st CoP
AT Refe		WIRJCTL161385 Please turn over for DISCLAIMER
JTHORIS	SED SIGNATORY	tathoremseidaz
	y the state of the	