TAC/Reference No. | C | N | 2

Date: 01st November 2022

Total Cert Dwg 02 pgs

TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non-Transferable Customer's Name M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11. **2**5.0 Customer's Address DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. Superior Shared Services, S de R.L. Manufacturing / Assembly Plant Address Via Lombardia #5705 2do Piso, Colonia Saucito Chihuahua-31110, Mexico Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service 7 1/2Jx18 H2 Size of Wheel Rim 6883522 Part No. Description of the Test Component(s) 7 1/2JX18H2 IS25 C# 004399/2019 MEXICO E S15 22 BMW 6883522 HT/X Identification No. / Marking >AISi7< **BMW Applicable Vehicle Model** 5 Applicable Notified Standard IS: 9436 -2018 with Amend. No.1, February 2021 6 Test Report No. CT0CR2026 dated 01.11.2022 6.1 List of supporting documents Drawing No. 6 883 522 **₹**° Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System 8 Not Applicable (QMS) BM9 Approval Granted/Not Granted/Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of production & 1st CoP shall be completed before 30.09,2024. ICAT Reference CCTNBMWIRJCTL161385 Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** FOR AUT HARISH JOSHI AMIT KARWAL PAMELA TIKKU Page 1 or Manager **Deputy General Manager** Officiating Director-ICAT