COP Certificate No. | C | C | 0 | C | S | 0 0 1 5 |

C C0CS0 0 1 5

Date : 5nd Jan. 2023

Cert	Dwg	Total
1	0	01 pgs

CERTIFICATE FOR CONFORMITY OF PRODUCTION

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. BMW India Pvt. Ltd.
2	Customer's Address	2nd Floor, Oberoi Centre, Building No. 11, DLF Cyber City, Phase – II, Gurugram - 122 002, Haryana, India.
3	Component Detail	Rear View Mirror (Class III)
4	Name and Address of Component Manufacturer	M/s. MAGNA Mirrors of America, Inc. 5085 Kraft Avenue SE Kentwood, MI 49512, USA
Meets all the test requirements as per ECE R46 / AIS:001 (Part 1) (Rev.1)-2011 as well as the requirements of Conformity of Production (COP) in accordance with Automotive Industry Standard AIS-037 with its Amend. No. 10.		
Valid Until: ** May change subjected to any further amendement in AIS : 037*		29.04.2024
Reference test report number		CoP Compliance statement no. UCY555471 dated 09.03.2022
Previous COP Certificate number		CC0CR0647 dated 06.04.2022, CC0CO1356 dated 31.07.2019
TAC References		CH1637

ICAT Reference	163777	Please turn over for DISCLAIMER

AUTHORISED SIGNATORY

CC0CS00155ndJan.2023M/s.BMWIndiaPvt.Ltd.CC0CS00155ndJan.2023M/s.BMWIn	CC0CS00155ndJan.2023M/s.BMWIndiaPvt.Ltd.CC0CS00155ndJan.2023M/s.BMWI	INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY ICAT Innovation • Service • Excellence MANESAR	CC0CS00155ndJan.2023M/s.BMWIndiaPvt.Ltd.CC0CS00155ndJan.2023M/s.BMWIndiaPvt.	ICAT Innovation • Service • Excellence
HARISH JOSHI Manager	AMIT KARWAL Deputy General Manager		Dr. MADHUSUDAN JOSHI Deputy General Manager	Page 1 of 1