



COP Certificate No. **C C O C S 0 5 8 7**

C COCSO 5 8 7

Date : 21st March 2023

Cert	Dwg	Total
1	0	01 pgs



CERTIFICATE FOR CONFORMITY OF PRODUCTION

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. Krishna Ishizaki Auto Ltd.
2	Customer's Address	58th KM Stone, Delhi Jaipur Highway, Village Binola, Gurgaon, India
3	Manufacturer of & Name/address of the Manufacturer	Rear View Mirror (Class I & III) Same as mentioned at S. No. 1 & 2 above
Meets all the test requirements as per AIS:001 (Part 1) (Rev.1):2011 as well as the requirements of Conformity of Production (COP) in accordance with Automotive Industry Standard AIS-037 with its Amend. No. 10.		
Valid Until: * May change subjected to any further amendement in AIS : 037		31.03.2025
Reference test report number		CT0CS0586 dated 21.03.2023
TAC Reference		C90493, C90494, C90495, C90496, C90497, C90498, C90499, C90500, C90501, C90502, CA0108, CA1722, CC0077, CD1651, CE1722, CH1296, CH1766, CH2639, CJ0264, CK0971, CK0973, CK1440, CP0165
Previous COP Certificate number		CC0C01165 dated 08.07.2019, CC0CQ0864 dated 25.03.2021
 		
ICAT Reference		CTL_74
Please turn over for DISCLAIMER		
AUTHORISED SIGNATORY		
HARISH JOSHI Manager		AMIT KARWAL Deputy General Manager
<small>CC0CS058721stMarch2023M/s. KrishnaIshizakiAutoLtd.CC0CS058721stMarch2023M</small>		<small>CC0CS058721stMarch2023M/s. KrishnaIshizakiAutoLtd.CC0CS058721stMarch2023M</small>
Dr. MADHUSUDAN JOSHI Deputy General Manager		Page 1 of 1