

COP Certificate No.

C	C	0	C	S	1	1	6	0
---	---	---	---	---	---	---	---	---

C CQCS1 1 6 0

Date : 09th June 2023


Cert	Dwg	Total
1	0	01 pgs

**CERTIFICATE FOR CONFORMITY OF PRODUCTION**

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. Caterpillar India Pvt. Ltd.
2	Customer's Address	Engineering Design Center, International Technology Park, Chennai, Taramani Road, Taramani, Chennai - 600 113 India
3	Importer of & Name & address of the Manufacturer	Rear View Mirror (Class II/III) M/s. Britax PMG Limited, Bessingby Industrial Estate, Bridlington, East Yorkshire, YO16 4SJ, United Kingdom
Meets all the test requirements as per AIS:001 (Part 1) (Rev.1):2011 as well as the requirements of Conformity of Production (COP) in accordance with Automotive Industry Standard AIS-037 with its Amend. No. 10.		
Valid Until: * May change subjected to any further amendment in AIS : 037		31.03.2025
Reference test report number		CT0CS1159 dated 09.06.2023
TAC Reference		CH0487 dated 14.06.2017
Previous COP Certificate number		CC0CP1737 dated 12.11.2020 CC0CQ1341 dated 01.06.2021

ICAT Reference	CTL_446	Please turn over for DISCLAIMER	
AUTHORISED SIGNATORY			
<small>CC0CS116009#June2023M#CaterpillarIndiaPvt.Ltd.CC0CS116009#June2023M#C</small>	<small>CC0CS116009#June2023M#CaterpillarIndiaPvt.Ltd.CC0CS116009#June2023M#C</small>		
HARISH JOSHI Manager	AMIT KARWAL Deputy General Manager		