COP Certificate No. CCOOCS 1877

37.

Date: 29th September 2023

39	Cert	Dwg	Total
	1 8100	0	01 pgs

CERTIFICATE FOR CONFORMITY OF PRODUCTION

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. Toyota Kirloskar Motor Pvt. Ltd.			
2	Customer's Address	Plot No. 1, Bidadi Industrial Area, Bidadi, Ramnagar, Dist., Pin-562109, Karnataka, India.			
3	Manufacturer of Control Control	Door Latch & Door Striker Assembly			
্ৰ 4	Name of the Manufacturer :	M/s. Aisin Corporation			
5 Indust	Address of the Manufacturing Plant:	Shinkawa Plant, 4-75 Rokken-cho, Hekinan-shi, Aichi 447-0861, Japan			
	the test requirements as per IS:14225-2017 (F	irst Revision) as well as the requirements of Conformity of Production rd AIS-037 with its Amend. No. 10.			
Valid Unti * May cha : 037	il: nge subjected to any further amendement in AIS	5 30.09.2025 Ruberial Ruberial Ruberial Ruber Block Ruberial Ruber Block Ruber			
Reference test report number TAC Reference		CT0CS1876 dated 29.09.2023			
		CH2330 dated 27.10.2017/ CT1CQ2638 dated 28.10.2021			
Durante and COD Contiffed to Name to add		COP Exemption Certificate No.: CC0CO1748 dated 26.09.2019			
Previous	COP Certificate Number	COP Exemption Certificate No.: CC0CQ2153 dated 31.08.2021			
-differen	1 Million State of the State of	Service (Modern Service)			

ICAT Reference	CCCTKMLSJCT	L169244	Please turn over for DISCLAIMER	
AUTHORISED SIGNATORY	Square 1 km	Meg 104	a. the killos and	3° notor
COCS 197729h-September 2020Mis. ToyotaKirloskanMotorPal Liki PowNo. 1. Bidadiindustr	Gild Hill Control of the Control of	INTO Service - Excellence	COCS1877296SeptemigroQCZMW. ToyclobicinoskantociarPogLick Fooths I, Biscald	Particular & Survice & Excellence
AMOL KUMAR	PRITAM SINGH SAWARIYA	Will the state of	SAURABH DALELA	Page 1 of
Deputy Manager	്റ്റ്. Manager	*MANESAR *	Director	
He toldy the set they to	a kindskal be edi. Ramadar. Kindskal Indi	of Day Lider	diversion "Fight Mo.	om:507108.