



COP Certificate No. **C C 0 C S 1 9 0 5**

C C 0 C S 1 9 0 5

Date : 30th Sep 2023

Cert	Dwg	Total
1	0	1 pg



CERTIFICATE FOR CONFORMITY OF PRODUCTION

(For compliance to AIS - 037)

Non- Transferable

1	Name of the Customer :	M/s. Guangdong Dahao Vehicle Accessory Industry & Commerce Co. Ltd.	
2	Address of the Customer:	Factory A, No.101, Zhuhe Road, Haojiang district, Shantou City, Guangdong Province (515098)	
3	Name of the Component Manufacturer :	M/s. Guangdong Dahao Vehicle Accessory Industry & Commerce Co. Ltd.	
4	Address of the Component Manufacturing Plant:	Factory A, No.101, Zhuhe Road, Haojiang district, Shantou City, Guangdong Province (515098)	
5	Manufacturer of:	Safety Belt Assembly	
6	Nomenclature:	3 Point Safety Belt Assembly with ELR for 2 nd Row RH/LH Seats	
7	Part Nos.:	2 nd Row RH Safety Belt Assy.	24323284
		2 nd Row LH Safety Belt Assy.	24323281
8	Applicable for Vehicle Model:	E230R	

Meets all the test requirements as per IS:15140-2018, Amend. 1, Feb 2022 as well as the requirements of Conformity of Production (COP) in accordance with Automotive Industry Standard AIS-037 with its Amend. No. 10.

Valid Until:	30.09.2024
* May change subjected to any further amendment in AIS : 037	
Reference Test Report number(s):	CT0CS1904 dated 30.09.2023
TAC Reference:	TAC No. CN1528 dated 19.12.2022
Previous COP Certificate number(s):	--

ICAT Reference **CTL_570** Please turn over for DISCLAIMER

AUTHORISED SIGNATORY

AMOL KUMAR Deputy Manager	PRITAM SINGH SAWARIYA Sr. Manager		SAURABH DALELA Director	Page 1 of 1 1