

COP Certificate No.

C	C	0	C	S	2	3	3	0
---	---	---	---	---	---	---	---	---

C C0CS2 3 3 0




Date : 20th December 2023

Cert	Dwg	Total
1	0	01 pgs

**CERTIFICATE OF CONFORMITY OF PRODUCTION**

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. Ningbo SMR Huaxiang Automotive Mirror Ltd.		
2	Customer's Address	Xizhou Industrial Zone, Xiangshan County-315722, Ningbo, Zhejiang, Province, China		
3	Description of component	Main Exterior Rear View Mirror (Class III)		
4	Name & address of the Manufacturer	Same as mentioned at S. No. 1 & 2 above		
Meets all the test requirements as per AIS:001 (Part 1) (Rev. 01):2011 as well as the requirements of Conformity of Production (COP) in accordance with Automotive Industry Standard AIS-037 with its Amend. No. 10.				
Valid Until: <i>* May change subjected to any further amendement in AIS : 037</i>		30.09.2025		
Reference test report number		CT0CS2329 dated 08.12.2023		
TAC Reference		CH2118 dated 23.10.2017 CM1921 dated 20.08.2021		
Previous COP Certificate number		CC0CP0788 dated 31.07.2020 & CC0CQ2543 dated 18.10.2021		
ICAT Reference		170266		
AUTHORISED SIGNATORY		Please turn over for DISCLAIMER		
<small>CC0CS233020InDecember2023M/s.NingboSMRHuaxiangAutomotiveMirrorLtd.CC0CS23</small>	<small>CC0CS233020InDecember2023M/s.NingboSMRHuaxiangAutomotiveMirrorLtd.CC0CS23</small>			
AMOL KUMAR Deputy Manager	PRITAM SINGH SAWARIYA Senior Manager	SAURABH DALELA Director	Page 1 of 1	