





COP Certificate No. **C C 0 C T 1 6 4 5****C C 0 C T 1 6 4 5**Date : 13<sup>th</sup> Sep. 2024

Cert	Dwg	Total
1	0	01 pgs

**CERTIFICATE FOR CONFORMITY OF PRODUCTION**

(For compliance to AIS - 037)

**Non- Transferable**

1	<b>Customer's Name</b>	<b>M/s. Fiem Industries Ltd. (Unit VII)</b>	
2	<b>Customer's Address</b>	<b>Plot No. 1915, Rai Industrial Estate, Phase V, Sonapat-131029, Haryana</b>	
3	<b>Manufacturer of:</b>	<b>Main Exterior Rear View Mirror (Class L)</b>	
4	<b>Name of the Manufacturer :</b>	<b>M/s. Fiem Industries Ltd. (Unit II)</b>	
5	<b>Address of the Manufacturing Plant:</b>	<b>219/2B, Hosur-Thally Road, Kallukondapalli, Belagondapalli P.O., Hosur -635114 Tamilnadu, India</b>	
<b>Meets all the test requirements as per AIS:001 (P2) (Rev.1):2011 as well as the requirements of Conformity of Production (COP) in accordance with Automotive Industry Standard AIS-037 with its Amend. No. 9.</b>			
<b>Valid Until:</b> <i>* May change subjected to any further amendment in AIS 037</i>		<b>30.09.2026</b>	
<b>Reference test report number</b>		<b>CT0CT1644 dated 13.09.2024</b>	
<b>TAC/Ext. TAC/ Ext. T.R. Reference</b>		<b>A91635, CT1CF1975, A91652, A91544, CT1CH0829, CT2CO2316, CT2CO1349, CT1CN1338, CT3CQ0975, A91538, CD1851, CT1CJ1530, CL1048, CT1CQ1298, CL1949, CT1CQ2005, CT2CT1264, A94307, CT7CR1620, CL 0381, CR 0105, CT0CT0104</b>	
<b>Previous COP Certificate number</b>		<b>CC0CN1856 dated 12.09.2018, CC0CP1309 dated 28.09.2020 CC0CR1732 dated 26.09.2022</b>	
<b>ICAT Reference</b>		<b>176081</b>	<b>Please turn over for DISCLAIMER</b>
<b>AUTHORISED SIGNATORY</b>			
<b>AMOL KUMAR Deputy Manager</b>		<b>PRITAM SINGH SAWARIYA Senior Manager</b>	
			
			
		<b>SAURABH DALELA Director</b>	
			
		<b>Page 1 of 1</b>	