

COP Certificate No. **C C 0 C T 1 8 9 2**

C COCT1 8 9 2

Date : 30th Sep. 2024

Cert	Dwg	Total
1	0	01 pgs






CERTIFICATE FOR CONFORMITY OF PRODUCTION

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. JSW MG Motor India Pvt. Ltd.
2	Customer's Address	10th Floor 32nd Milestone, NH-8, Sec. 15 Gurgaon, Haryana
3	Manufacturer of:	Rear View Mirror
4	Name of the Manufacturer :	M/s. Shanghai Ganxiang Automobile Mirror Industry Co., Ltd.
5	Address of the Manufacturing Plant:	No.4000 Zhu-Lv Rd, Ganxiang Town, Jinshan District, Shanghai City, P.R.China
Meets all the test requirements as per AIS:001 (Part 1) (Rev.1):2011 as well as the requirements of Conformity of Production (COP) in accordance with Automotive Industry Standard AIS-037 with its Amend. No. 9.		
Valid Until: <i>* May change subjected to any further amendment in AIS 037</i>		30.09.2026
Reference test report number		CT0CT1891 dated 30.09.2024
TAC/Ext. TAC/ Ext. T.R. Reference		Refer Test Report no. CT0CT1891 dated 30.09.2024
Previous COP Certificate number		CC0CR2256 dated 20.12.2022

ICAT Reference	178645	Please turn over for DISCLAIMER	
AUTHORISED SIGNATORY			
AMOL KUMAR Deputy Manager	PRITAM SINGH SAWARIYA Senior Manager		 SAURABH DALELA Director
			 Page 1 of 1