

TAC/Reference No. **C N 2 3 2 5****C N2325**Date : 21st December 2022

Cert	Dwg	Total
1	1	02 pgs

**TYPE APPROVAL CERTIFICATE**

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. BMW India Private Limited
2	Customer's Address	2nd Floor, Oberoi Centre, Building No. 11, DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India
3	Manufacturing / Assembly Plant Address	M/s. Borbet Germany GmbH, 59969 Hallenberg-Hesborn, Germany.
4	Description of the Test Component(s)	Type of Wheel Rim Aluminium Alloy Wheel Rim for Passenger Cars-Normal Highway Service
		Size of Wheel Rim 7 1/2Jx18 H2
		Part No. 8746631
		Identification No. / Marking BM 00375 K1>AISi7< T F IS25 7 1/2Jx18H2 DE 21 BTG22 000167/2014 BMW 8746631
		Applicable Vehicle Model BMW
5	Applicable Notified Standard	IS: 9436 -2018 with Amend. No.1, February 2021
6	Test Report No.	CT0CR2324 dated 20.12.2022
6.1	List of supporting documents	Drawing No. 8746631
7	Pre-test inspection Visit Report No.	Not Applicable
8	Details of Quality Management System (QMS)	Not Applicable
9	Approval	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Granted/ Not Granted/ Extended
10	The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of production & 1st CoP shall be completed before 30.09.2024.	
ICAT Reference		CCTNBWIRNCTL164047
AUTHORISED SIGNATORY		Please turn over for DISCLAIMER
HARISH JOSHI Manager		AMIT KARWAL Deputy General Manager
<small>CN232521stDecember2022M/s. BMWIndiaPrivateLimitedCN232521stDecember2022M/s.</small>		<small>CN232521stDecember2022M/s. BMWIndiaPrivateLimitedCN232521stDecember2022M/s.</small>
<small>CN232521stDecember2022M/s. BMWIndiaPrivateLimitedCN232521stDecember2022M/s.</small>		<small>CN232521stDecember2022M/s. BMWIndiaPrivateLimitedCN232521stDecember2022M/s.</small>
Dr. MADHUSUDAN JOSHI Deputy General Manager		Page 1 of 1