

TAC/Reference No. C N 2 3 2 9

Manager

Deputy General Manager

Date: 21st December 2022

Deputy General Manager

1	Cert	Dwg	√Total
	1,5	1	02 pgs

TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non- Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11, 2 Customer's Address DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. Borbet Austria GmbH Manufacturing Assembly Plant Address Lamprechtshausener Str. 77, A-5282 Ranhofen, Austria Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 8 1/2Jx18 H2 Part No. 8089891 Description of the Test Component(s) 8 1/2JX18H2 IS 40 K1 BMW AT BAT 21 22 >AISi7< T BM00350 8089891 Identification No. / Marking 004684/2014 BMW³¹ Applicable Vehicle Model Applicable Notified Standard 5 IS: 9436 -2018 with Amend. No.1, February 2021 6 Test Report No. CT0CR2328 dated 20.12.2022 List of supporting documents Drawing No. 8089891 6.1 **7** Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System 8 Not Applicable (QMS) 9 Approval Granted/ Not Granted/ Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of production & 1st CoP shall be completed before 30,09,2024. ICAT Reference CCTNBMWIRNCTL164047 Please turn over for DISCLAIMER AUTHORISED SIGNATORY Page 1 o HARISH JOSHI AMIT KARWAL Dr. MADHUSUDAN JOSHI