



TAC/Reference No. **C N 2 3 3 1****C N2331**Date : 21st December 2022

Cert	Dwg	Total
1	1	02 pgs

**TYPE APPROVAL CERTIFICATE**

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. BMW India Private Limited	
2	Customer's Address	2nd Floor, Oberoi Centre, Building No. 11, DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India	
3	Manufacturing / Assembly Plant Address	M/s. Borbet Austria GmbH Lamprechtshausener Str. 77, A-5282 Ranhofen, Austria	
4	Description of the Test Component(s)	Type of Wheel Rim	Aluminium Alloy Wheel Rim for Passenger Cars-Normal Highway Service
		Size of Wheel Rim	7 1/2Jx17 H2
		Part No.	6883517
		Identification No. / Marking	7915323 SIL BAT BMW 7 1/2JX17 H2 AT IS 30 BM0 0343 6883517 GRE 000176/2014 > AISi7 < T K1 23 22
		Applicable Vehicle Model	BMW
5	Applicable Notified Standard	IS: 9436 -2018 with Amend. No.1, February 2021	
6	Test Report No.	CT0CR2330 dated 20.12.2022	
6.1	List of supporting documents	Drawing No. 6883517	
7	Pre-test inspection Visit Report No.	Not Applicable	
8	Details of Quality Management System (QMS)	Not Applicable	
9	Approval	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Granted/ Not Granted/ Extended	
10	The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of production & 1st CoP shall be completed before 30.09.2024.		
ICAT Reference		CCTNBWIRNCTL164047	Please turn over for DISCLAIMER
AUTHORISED SIGNATORY			
			
<small>CN233121stDecember2022M/s. BMWIndiaPrivateLimitedCN233121stDecember2022M/s.</small> HARISH JOSHI Manager		<small>CN233121stDecember2022M/s. BMWIndiaPrivateLimitedCN233121stDecember2022M/s.</small> AMIT KARWAL Deputy General Manager	
<small>CN233121stDecember2022M/s. BMWIndiaPrivateLimitedCN233121stDecember2022M/s.</small> Dr. MADHUSUDAN JOSHI Deputy General Manager		<small>CN233121stDecember2022M/s. BMWIndiaPrivateLimitedCN233121stDecember2022M/s.</small> Page 1 of 1	