





TAC/Reference No. **C N 2 3 7 2****C N2372**Date : 27th December 2022

Cert	Dwg	Total
1	1	02 pgs

**TYPE APPROVAL CERTIFICATE**

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. BMW India Private Limited	
2	Customer's Address	2nd Floor, Oberoi Centre, Building No. 11, DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India	
3	Manufacturing / Assembly Plant Address	M/s. Borbet Germany GmbH, 59969 Hallenberg-Hesborn, Germany.	
4	Description of the Test Component(s)	Type of Wheel Rim	Aluminium Alloy Wheel Rim for Passenger Cars-Normal Highway Service
		Size of Wheel Rim	8 1/2Jx18 H2
		Part No.	8746632
		Identification No. / Marking	F K1 >A1Si7< DE21 BTG BM00376  004391/2014  BMW 8746632 8 1/2JX18H2 IS 40 T V
		Applicable Vehicle Model	BMW
5	Applicable Notified Standard	IS: 9436 -2018 with Amend. No.1, February 2021	
6	Test Report No.	CT0CR2371 dated 26.12.2022	
6.1	List of supporting documents	Drawing No. 8746632	
7	Pre-test inspection Visit Report No.	Not Applicable	
8	Details of Quality Management System (QMS)	Not Applicable	
9	Approval	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Granted/ Not Granted/ Extended	
10	The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of production & 1st CoP shall be completed before 30.09.2024.		
ICAT Reference		CCTNBMWIRNCTL164047	Please turn over for DISCLAIMER
AUTHORISED SIGNATORY			
<small>CN237227thDecember2022M/s.BMWIndiaPrivateLimitedCN237227thDecember2022M/s.</small>		<small>CN237227thDecember2022M/s.BMWIndiaPrivateLimitedCN237227thDecember2022M/s.</small>	
HARISH JOSHI Manager		AMIT KARWAL Deputy General Manager	
			
<small>CN237227thDecember2022M/s.BMWIndiaPrivateLimitedCN237227thDecember2022M/s.</small>		<small>CN237227thDecember2022M/s.BMWIndiaPrivateLimitedCN237227thDecember2022M/s.</small>	
Dr. MADHUSUDAN JOSHI Deputy General Manager		Page 1 of 1	