






TAC/Reference No. **C N 2 3 8 2****C N2382**Date : 27th December 2022

Cert	Dwg	Total
1	1	02 pgs

**TYPE APPROVAL CERTIFICATE**

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. BMW India Private Limited	
2	Customer's Address	2nd Floor, Oberoi Centre, Building No. 11, DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India	
3	Manufacturing / Assembly Plant Address	M/s. Ronal Polska Sp.zo.o., Walbrzych ul Wroclawska 95-PL-58306 Walbrzych, Poland.	
4	Description of the Test Component(s)	Type of Wheel Rim	Aluminium Alloy Wheel Rim for Passenger Cars-Normal Highway Service
		Size of Wheel Rim	9 1/2Jx21 H2
		Part No.	6885141
		Identification No. / Marking	6885461BLA 6885141GRE DOT 18 RONAL 4317 2 PL X Wa L E 9 1/2JX21 H2 IS36 >A1Si7< BMW 
		Applicable Vehicle Model	BMW
5	Applicable Notified Standard	IS: 9436 -2018 with Amend. No.1, February 2021	
6	Test Report No.	CT0CR2381 dated 27.12.2022	
6.1	List of supporting documents	Drawing No.6885141	
7	Pre-test inspection Visit Report No.	Not Applicable	
8	Details of Quality Management System (QMS)	Not Applicable	
9	Approval	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Granted/ Not Granted/ Extended	
10	The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of production & 1st CoP shall be completed before 30.09.2024.		
ICAT Reference		CCTNBWIRNCTL164047	Please turn over for DISCLAIMER
AUTHORISED SIGNATORY			
			
HARISH JOSHI Manager		AMIT KARWAL Deputy General Manager	
			
		Dr. MADHUSUDAN JOSHI Deputy General Manager	
			Page 1 of 1