TAC/Reference No. | C | N | 2

HARISH JOSHI

Manager

Date: 27th December 2022

Dr. MADHUSUDAN JOSHI

Deputy General Manager

3	g 410		
1	Cert	Dwg	√Total
ſ	1,	1 , 4	02 pgs

TYPE APPROVAL CERTIFICATE (For compliance to AIS - 037) Non- Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11, 2 Customer's Address DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. Ronal GmbH. Manufacturing / Assembly Plant Address Land kommissar Strasse 18, D-76829, Landau-42079, Germany Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 9 1/2Jx21 H2 Part No. 8071998 Description of the Test Component(s) RONAL 8 4287 5A2A380G0 BMW 8071998 22 REG003670/2017 DOT A Wa X E Identification No. / Marking 9 1/2JX21H2 IS37 DE >A1Si7< BMW Applicable Vehicle Model Applicable Notified Standard 5 IS: 9436 -2018 with Amend. No.1, February 2021 6 Test Report No. CT0CR2391 dated 27.12.2022 List of supporting documents **Drawing No.8071998** 6.1 **7** Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System Not Applicable 8 (QMS) 9 Approval Granted/ Not Granted/ Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of production & 1st CoP shall be completed before 30,09,2024. ICAT Reference CCTNBMWIRNCTL164047 Please turn over for DISCLAIMER AUTHORISED SIGNATORY Page 1 o

AMIT KARWAL

**Deputy General Manager**