TAC/Reference No. CPP 0 0 3 9

Deputy Manager

Deputy General Manager

Deputy General Manager

Date: 17th January 2023

S	Cert	^{্ট} Dwg	Total
	1 BIRM	1 ,00	02 pgs

TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non-Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11, Customer's Address 23 DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. CMS Jant ve Makine Snavii. Manufacturing / Assembly Plant Address A.S. AOSB 10006/1 Sk. 12, 35620-Cigli, Izmir, Turkey Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 9JX20 H2 Part No. 5A19DE4 Description of the Test Component(s) BMW TURKEY 002072/2015 CMS GZ IS 24 9J X 20H2 5A19DE4 CMS 1309-1 >A1Si7< Identification No. / Marking HTCXBSGT BM₩ Applicable Vehicle Model 5 Applicable Notified Standard IS: 9436 -2018 with Amend. No.1, February 2021 60 Test Report No. CT0CS0038 dated 17.01.2023 List of supporting documents 6.1 Drawing No. 5A19DE4 Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System 8 Not Applicable (QMS) 8 Mg Approval Granted/Not Granted/Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1st CoP shall be completed before 31.03.2025. CCTNBMWIRMCTL163165 ICAT Reference Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** Page 1 of AMOL KUMAR AMIT KARWAL Dr. MADHUSUDAN JOSHI