TAC/Reference No. C P 0 0 5 3

Date: 10th January 2023

Cert _c	[©] Dwg	Total
1,45	1 10	ິ02 pgs

TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non- Transferable M/s. CROMODORA WHEELS S.p.A., **Customer's Name** Customer's Address Via Montichiari 20, 25016 Ghedi (BS), Italy Manufacturing / Assembly Plant Address 3 Same as mentioned in Sr. No.1 & 2 above. Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 8Jx18 H2 4K0.601.025.BH Part No. MADE IN ITALY Description of the Test Component(s) Identification No. / Marking Applicable Vehicle Model Audi C8 (A6) IS: 9436-2018 with Amend. No.1, February 2021 5 Applicable Notified Standard Test Report No. CT0CS0052 dated 10.01.2023 6 List of supporting documents 6.1 Drawing No. CD582 Pre-test inspection Visit Report No. SHL/310/2014-2015/4893/2824 dated 26.12.2014 Details of Quality Management System IATF 16949:2016; IATF Certificate No. 0384413 valid upto 04.02.2024 8 (QMS) √9 Approval Granted/ Not Granted/ Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of production & 1st CoP shall be completed before 31.03.2025. ICAT Reference CCTNCRDRRLCTL162415 Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** Page 1 of HARISH JOSHI AMIT KARWAL Dr. MADHUSUDAN JOSHI Manager **Deputy General Manager** Deputy General Manager