TAC/Reference No. C P 0 1 3

Date: 23rd January 2023

CP01/13

Cert Dwg Total

TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non-Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11, Customer's Address 23 DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. CMS Jant ve Makine Snavii. Manufacturing / Assembly Plant Address A.S. AOSB 10006/1 Sk. 12, 35620-Cigli, Izmir, Turkey Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 9Jx20 H2 Part No. 5A19DF8 Description of the Test Component(s) BMW 002072/2015 IS 26 CNS GZ TURKEY 9Jx20H2 5A19DF8 CMS 1321-Identification No. / Marking 1>A1Si7< 22 HT B S C X G T Applicable Vehicle Model **BMW** 5 Applicable Notified Standard IS: 9436 -2018 with Amend. No.1, February 2021 600 Test Report No. CT0CS0112 dated 23.01.2023 List of supporting documents 6.1 Drawing No. 5A19DF8 .**7**% Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System 8 Not Applicable (QMS) 8 Mg Approval Granted/Not Granted/Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1st CoP shall be completed before 31.03.2025. CCTNBMWIRMCTL163165 ICAT Reference Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** HARISH JOSHI AMIT KARWAL Dr. MADHUSUDAN JOSHI Page 1 of Manager **Deputy General Manager** Deputy General Manager