TAC/Reference No. C P 0 1 1 5

Date: 25th January 2023

	Cert	(^{Č)T®} Dwg	Total
Г	1 Bh	1 01	⁰ 02 pgs ្ត

TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non-Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11, Customer's Address 23 DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. CMS Jant ve Makine Snavii. Manufacturing / Assembly Plant Address A.S. AOSB 10006/1 Sk. 12, 35620-Cigli, Izmir, Turkey Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 10 1/2Jx20 H2 Part No. 5A19DE7 Description of the Test Component(s) CMS1312-1 >A1Si7<BMW TURKEY Identification No. / Marking 005548/2021 CMS GZ 22 IS 44 10 1/2Jx20H2 5A19DE7 HTCXBSGT BM₩ Applicable Vehicle Model 5 Applicable Notified Standard IS: 9436 -2018 with Amend. No.1, February 2021 600 Test Report No. CT0CS0114 dated 25.01.2023 List of supporting documents 6.1 Drawing No. 5A19DE7 **.7**01 Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System 8 Not Applicable (QMS) 8 Mg Approval Granted/Not Granted/Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1st CoP shall be completed before 31.03.2025. CCTNBMWIRMCTL163165 ICAT Reference Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** Page 1 of HARISH JOSHI AMIT KARWAL Dr. MADHUSUDAN JOSHI Manager **Deputy General Manager** Deputy General Manager