

TAC/Reference No. CP 0 1 7

Date: 24th January 2023

CP01

Cert	Dwg	Total
1 BM	1 0	02 pgs

## TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non-Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11, Customer's Address 23 DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. CMS Jant ve Makine Snavii, Manufacturing / Assembly Plant Address A.S. AOSB 10006/1 Sk. 12, 35620-Cigli, Izmir, Turkey Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 8 1/2Jx19 H2 Part No. 5A19DE3 Description of the Test Component(s) BMW 5A19DE3 22 21 CMS 1308-1 TURKEY Identification No. / Marking CMS GZ >A1Si7< 8 1/2Jx19H2 IS 26 001049/2014 HT C X B S G T BM₩ Applicable Vehicle Model 5 Applicable Notified Standard IS: 9436 -2018 with Amend. No.1, February 2021 600 Test Report No. CT0CS0116 dated 24.01.2023 List of supporting documents 6.1 Drawing No. 5A19DE3 1**7**01 Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System 8 Not Applicable (QMS) 8 Mg Approval Granted/Not Granted/Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1st CoP shall be completed before 31.03.2025. CCTNBMWIRMCTL163165 ICAT Reference Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** Page 1 of HARISH JOSHI AMIT KARWAL Dr. MADHUSUDAN JOSHI Manager **Deputy General Manager** Deputy General Manager