

TAC/Reference No. **C P 0 1 1 9**

CP0119





Date : 27th February 2023

Cert	Dwg	Total
1	1	02 pgs

**TYPE APPROVAL CERTIFICATE**

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. BMW India Private Limited	
2	Customer's Address	2nd Floor, Oberoi Centre, Building No. 11, DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India	
3	Manufacturing / Assembly Plant Address	M/s. CMS Jant ve Makine Snayii, A.S. AOSB 10006/1 Sk. 12, 35620-Cigli, Izmir, Turkey	
4	Description of the Test Component(s)	Type of Wheel Rim	Aluminium Alloy Wheel Rim for Passenger Cars-Normal Highway Service
		Size of Wheel Rim	10 1/2J X 20 H2
		Part No.	5A19DF9
		Identification No. / Marking	BMW  005548/2021 IS44 CMS GZ TURKEY 10 1/2Jx20H2 5A19DF9 CMS 1322-1 >A1Si7< 22  HT C X B S G T
		Applicable Vehicle Model	BMW
5	Applicable Notified Standard	IS: 9436 -2018 with Amend. No.1, February 2021	
6	Test Report No.	CT0CS0118 dated 27.02.2023	
6.1	List of supporting documents	Drawing No. 5A19DF9	
7	Pre-test inspection Visit Report No.	Not Applicable	
8	Details of Quality Management System (QMS)	Not Applicable	
9	Approval	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Granted/ Not Granted/ Extended	
10	The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1st CoP shall be completed before 31.03.2025.		
ICAT Reference		CCTNBWIRMCTL163165	Please turn over for DISCLAIMER
AUTHORISED SIGNATORY			
<small>CP011927thFebruary2023M/s.BMWIndiaPrivateLimitedCP011927thFebruary2023M/</small>		<small>CP011927thFebruary2023M/s.BMWIndiaPrivateLimitedCP011927thFebruary2023M/s</small>	
HARISH JOSHI Manager		AMIT KARWAL Deputy General Manager	
			
		Dr. MADHUSUDAN JOSHI Deputy General Manager	
			 Page 1 of 1