

TAC/Reference No. CP 0 2 2 7

Date: 07th February 2023

CP022

//		- 01
Cert	o Dwg	Total
1 BAR	1 ,02	02 pgs

## TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non-Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11, Customer's Address 23 DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. Tianjin Lizhong Alloy Group Co. Ltd. Manufacturing / Assembly Plant Address Industrial Park Xinchang County, Zhejiang, 312500, China Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 7 1/2Jx18 H2 Part No. 6891179 Description of the Test Component(s) BMW 06087 E7 1/2J X 18 001122/2017 DOT LZT CHINA 201423-11 6891179 Identification No. / Marking >A1Si7< 21 M1 IS 50 T6 X C M BM₩ Applicable Vehicle Model 5 Applicable Notified Standard IS: 9436 -2018 with Amend. No.1, February 2021 **6**000 Test Report No. CT0CS0226 dated 07.02.2023 List of supporting documents Drawing No. 6891179 6.1 Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System 8 Not Applicable (QMS) 8 Mg Approval Granted/Not Granted/Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1st CoP shall be completed before 31.03.2025. ICAT Reference CTL 34 Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** Page 1 of HARISH JOSHI AMIT KARWAL Dr. MADHUSUDAN JOSHI Manager **Deputy General Manager** Deputy General Manager