

TAC/Reference No. **C P 0 3 0 1**

CP0301

Date : 13th February 2023



Cert	Dwg	Total
1	1	02 pgs



TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. BMW India Private Limited	
2	Customer's Address	2nd Floor, Oberoi Centre, Building No. 11, DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India	
3	Manufacturing / Assembly Plant Address	M/s. Borbet Austria GmbH Lamprechtshausener Str. 77, A-5282 Ranhofen, Austria	
4	Description of the Test Component(s)	Type of Wheel Rim	Aluminium Alloy Wheel Rim for Passenger Cars-Normal Highway Service
		Size of Wheel Rim	7 1/2Jx18 H2
		Part No.	6891179
		Identification No. / Marking	6891179 BMW DOT T E7 1/2Jx18H2 BM00382 IS 50 004681/2014 >A1S17< K1. 22 AT 23 BAT V
		Applicable Vehicle Model	BMW
5	Applicable Notified Standard	IS: 9436 -2018 with Amend. No.1, February 2021	
6	Test Report No.	CT0CS0300 dated 13.02.2023	
6.1	List of supporting documents	Drawing No.6891179	
7	Pre-test inspection Visit Report No.	Not Applicable	
8	Details of Quality Management System (QMS)	Not Applicable	
9	Approval	<div style="display: flex; justify-content: space-around;"> √ X X </div> Granted/ Not Granted/ Extended	
10	The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1 st CoP shall be completed before 31.03.2025.		
ICAT Reference		CTL_34	Please turn over for DISCLAIMER
AUTHORISED SIGNATORY			
<small>CP030113thFebruary2023M/s.BMWIndiaPrivateLimitedCP030113thFebruary2023M/</small> HARISH JOSHI Manager		<small>CP030113thFebruary2023M/s.BMWIndiaPrivateLimitedCP030113thFebruary2023M/s</small>  Dr. MADHUSUDAN JOSHI Deputy General Manager	
<small>CP030113thFebruary2023M/s.BMWIndiaPrivateLimitedCP030113thFebruary2023M/s</small> AMIT KARWAL Deputy General Manager		<small>CP030113thFebruary2023M/s.BMWIndiaPrivateLimitedCP030113thFebruary2023M/s</small>  Page 1 of 1	