

TAC/Reference No. **C P 1 1 2 0**

CP1120

Date : 01st June 2023



Cert	Dwg	Total
1	1	02 pgs



TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. BMW India Private Limited	
2	Customer's Address	2nd Floor, Oberoi Centre, Building No. 11, DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India	
3	Manufacturing / Assembly Plant Address	M/s. Tianjin Lizhong Alloy Group Co. Ltd. Industrial Park Xinchang County, Zhejiang, 312500, China	
4	Description of the Test Component(s)	Type of Wheel Rim	Aluminium Alloy Wheel Rim for Passenger Cars-Normal Highway Service
		Size of Wheel Rim	7 1/2Jx18 H2
		Part No.	6898039
		Identification No. / Marking	BMW-M1 IS 50 06082 E7 1/2Jx18H2 001122/2017 DOT CHINA LZT 201423-11 6898039 >A1Si7< 22 T6 X C M
		Applicable Vehicle Model	BMW
5	Applicable Notified Standard	IS: 9436 -2018 with Amend. No.1, February 2021	
6	Test Report No.	CTOCS1119 dated 01.06.2023	
6.1	List of supporting documents	Drawing No.6898039	
7	Pre-test inspection Visit Report No.	Not Applicable	
8	Details of Quality Management System (QMS)	Not Applicable	
9	Approval	<div style="display: flex; justify-content: space-around;"> √ X X </div> Granted/ Not Granted/ Extended	
10	The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1 st CoP shall be completed before 31.03.2025.		
ICAT Reference		CTL_34	Please turn over for DISCLAIMER
AUTHORISED SIGNATORY			
<small>CP112001stJune2023M/s.BMWIndiaPrivateLimitedCP112001stJune2023M/s.BMWIn</small> HARISH JOSHI Manager		<small>CR112001stJune2023M/s.BMWIndiaPrivateLimitedCP112001stJune2023M/s.BMWIn</small> AMIT KARWAL Deputy General Manager	
			
			
		<small>CP112001stJune2023M/s.BMWIndiaPrivateLimitedCP112001stJune2023M/s.BMWIn</small> Dr. MADHUSUDAN JOSHI Deputy General Manager	
		Page 1 of 1	