TAC/Reference No. | C | P | 1 | 2 | 0 | 0

Date: 19th June 2023

Cert	of Kidlie	Dwg		Total	
1 👌	W.	1	22	02 pgs	.4

TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non-Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11, Customer's Address 23 DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. Borbet Austria GmbH Manufacturing / Assembly Plant Address Lamprechtshausener Str. 77, A-5282 Ranhofen, Austria Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 8Jx19 H2 Part No. 6898041 Description of the Test Component(s) 6898041 DOT BM00398 K1 >AISi7< BAT 22 BMW IS 46 E8J X 19H2 Identification No. / Marking 000384/2014 TCE 23 AT Applicable Vehicle Model **BMW** 5 Applicable Notified Standard IS: 9436 -2018 with Amend. No.1, February 2021 **6**0° Test Report No. CT0CS1199 dated 19.06.2023 List of supporting documents Drawing No.6898041 6.1 Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System 8 Not Applicable (QMS) 8 Mg **Approval** Granted/Not Granted/Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1st CoP shall be completed before 31.03.2025. ICAT Reference CTL 34 Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** Page 1 of HARISH JOSHI AMIT KARWAL Dr. MADHUSUDAN JOSHI Manager **Deputy General Manager** Deputy General Manager