TAC/Reference No. C P 1

Manager

**Deputy General Manager** 

Date: 17th July 2023

Deputy General Manager

ľ	Cert	<sup>্টি</sup> Dwg	Total
Γ	1 811	1 ,	<sup>0</sup> 02 pgs ្ត

## TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non-Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11, Customer's Address 23 DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. Tianjin Lizhong Alloy Group Co. Ltd. Industrial Park Xinchang Manufacturing / Assembly Plant Address County, Zhejiang, 312500, China Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 8Jx19 H2 Part No. 6898041 Description of the Test Component(s) BMW M1 06084 E8JX19H2 IS 46 004136/2018 DOT CHINA LZT 2014 23-11 6898041 >ALSi7< 22 C M T6 X Identification No. / Marking BM₩ Applicable Vehicle Model 5 Applicable Notified Standard IS: 9436 -2018 with Amend. No.1, February 2021 60 Test Report No. CT0CS1444 dated 17.07.2023 List of supporting documents Drawing No.6898041 6.1 Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System 8 Not Applicable (QMS) 8 Mg **Approval** Granted/Not Granted/Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1st CoP shall be completed before 31.03.2025. ICAT Reference CTL 34 Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** Page 1 of HARISH JOSHI **AMIT KARWAL** Dr. MADHUSUDAN JOSHI