TAC/Reference No. C P 1 4 7 7

Date : 20th July 2023

Cert Dwg Total

1 3 1 02 pgs

CP1477

TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non-Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 11, Customer's Address 23 DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. Borbet Austria GmbH Manufacturing / Assembly Plant Address Lamprechtshausener Str. 77, A-5282 Ranhofen, Austria Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 8Jx19 H2 Part No. 6898051 Description of the Test Component(s) E8JX19 H2 IS 46 BMW BM 00399 K1 Identification No. / Marking >ALSi7<22 AT 5A32885 GO 5A1E230 BLA 6898051 GRE 000384/2014 DOT T BAT **BMW** Applicable Vehicle Model 5 Applicable Notified Standard IS: 9436 -2018 with Amend. No.1, February 2021 60 Test Report No. CT0CS1476dated 20.07.2023 List of supporting documents Drawing No.6898051 6.1 **7** Pre-test inspection Visit Report No. Not Applicable Details of Quality Management System 8 Not Applicable (QMS) 8 Mg Approval Granted/Not Granted/Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1st CoP shall be completed before 30.09.2025. ICAT Reference CTL 34 Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** Page 1 of HARISH JOSHI AMIT KARWAL Dr. MADHUSUDAN JOSHI Manager **Deputy General Manager** Deputy General Manager