

TAC/Reference No. **C P 1 5 3 3**

CP1533

Date : 28th July 2023



Cert	Dwg	Total
1	1	02 pgs



TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037)

Non- Transferable

1	Customer's Name	M/s. BMW India Private Limited
2	Customer's Address	2nd Floor, Oberoi Centre, Building No. 11, DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India
3	Manufacturing / Assembly Plant Address	M/s. Tianjin Lizhong Alloy Group Co. Ltd. Industrial Park Xinchang County, Zhejiang, 312500, China
4	Description of the Test Component(s)	Type of Wheel Rim Aluminium Alloy Wheel Rim for Passenger Cars-Normal Highway Service
		Size of Wheel Rim 8Jx19 H2
		Part No. 6898051
		Identification No. / Marking BMW 06086 E8JX19H2 IS46 004136/2018 CHINA LZT DOT 201423-11 6898051 5A32885 >ALSi7< 22 M1 T6 X C M
		Applicable Vehicle Model BMW
5	Applicable Notified Standard	IS: 9436 -2018 with Amend. No.1, February 2021
6	Test Report No.	CT0CS1532dated 28.07.2023
6.1	List of supporting documents	Drawing No.6898051
7	Pre-test inspection Visit Report No.	Not Applicable
8	Details of Quality Management System (QMS)	Not Applicable
9	Approval	√ X X Granted/ Not Granted/ Extended
10	The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1 st CoP shall be completed before 30.09.2025.	
ICAT Reference		CTL_34
Please turn over for DISCLAIMER		
AUTHORISED SIGNATORY		
		
CP1533:28thJuly2023M/s.BMWIndiaPrivateLimitedCP1533:28thJuly2023M/s.BMWIndiaP	CP1533:28thJuly2023M/s.BMWIndiaPrivateLimitedCP1533:28thJuly2023M/s.BMWIndiaP	CP1533:28thJuly2023M/s.BMWIndiaPrivateLimitedCP1533:28thJuly2023M/s.BMWIndiaP
HARISH JOSHI Manager	AMIT KARWAL Deputy General Manager	Dr. MADHUSUDAN JOSHI Deputy General Manager
		Page 1 of 1