TAC/Reference No. C P 1 5 3 6

Date: 31st July 2023

**Deputy General Manager** 

D1586

Manager

**Deputy General Manager** 

	Qu., _0_0	01
Cert	Dwg	Total
1811	1 ,5	02 pgs 🦪

## TYPE APPROVAL CERTIFICATE

(For compliance to AIS - 037) Non-Transferable **Customer's Name** M/s. BMW India Private Limited 2nd Floor, Oberoi Centre, Building No. 14, 23 Customer's Address DLF Cyber City, Phase II, Gurgaon -122002, Haryana, India M/s. Borbet Austria GmbH Manufacturing / Assembly Plant Address Lamprechtshausener Str. 77, A-5282 Ranhofen, Austria Aluminium Alloy Wheel Rim for Passenger Type of Wheel Rim Cars-Normal Highway Service Size of Wheel Rim 8Jx19 H2 Part No. 5A1E230 Description of the Test Component(s) E 8JX19H2 IS46 BMW BM00399 K1 >ALSi7< 22 AT 5A32885 GO 5A1E230 BLA Identification No. / Marking 6898051 GRE 000384/2014 DOT PD T Applicable Vehicle Model BMW 5 Applicable Notified Standard IS: 9436 -2018 with Amend. No.1, February 2021 60 Test Report No. CT0CS1535dated 31.07.2023 List of supporting documents Drawing No.6898051 6.1 Pre-test inspection Visit Report No. Not Applicable **Details of Quality Management System** 8 Not Applicable (QMS) EN9 Approval Granted/ Not Granted/ Extended The CoP period for the component mentioned in Sr. No. 4 above shall begin from the date of commercial production of the vehicle model using that component & 1st CoP shall be completed before 30.09.2025. ICAT Reference CTL 34 Please turn over for DISCLAIMER **AUTHORISED SIGNATORY** Page 1 of HARISH JOSHI AMIT KARWAL Dr. MADHUSUDAN JOSHI