

ANNEXURE - II

Rule No.	Sub Rule(s)	Compliance Verified For		Standard
93	(1A)(IV), 1B,2,3,4	Motor Vehicle Width, Length and Height:		-
94	(1), (2) & (3)	Condition of tyres		-
95	(1), (2), (2A), (3) & (5)	Size & ply rating of tyres		-
		Front	18 - 25, 24 PR	
		Rear		
96-A	(1), (2), (3), (4), (5), (6) & (7)	Brakes for Construction Equipment Vehicles		AIS -143 - 2017
98-A	(1), (2)	Steering Gears for Construction Equipment Vehicles		IS/ISO - 7457:1997
	(3)			AIS -144 - 2018
99	-	Forward and backward motion		-
100	(1), (2) & (3)	Safety Glass		IS:2553 (Part 2)(Revision1):2019
101	(2A)	Windscreen Wiper		-
102	(1) & (2)	Signaling devices, direction indicators and stop lights		-
103	(1) & (2)	Position of the indicator		-
104-A	(i), (ii), (iii), (iv), (v), (vi) & (vii)	Fitment of reflectors on Construction Equipment Vehicles		AIS-057 (Rev. 1): 2010
105	(1)(d), (2) (ii), (3)(A), (6) & (8)	Lamps		-
106	(1)	Deflection of lights		-
107-A	-	Implement Lights for Construction Equipment Vehicles		-
108-A	-	Use of red or white light for Construction Equipment Vehicles		-
109	-	Parking light		-
111	-	Prohibition of spotlights etc.		-
114	(1) & (2)	Exhaust gases and exhaust pipes		-
115	(9)	Emission of smoke, vapour, etc. from Construction Equipment Vehicles		AIS -137 (Part 7-A1)
115 A	(10)			
117	(1) & (3)	Speedometer		IS 11827:2008
119	(1) & (3)	Horns		IS 1884:1992

ICAT Ref No.	2024-0544 ;IOCS NO. 178323
Emission Report No.	TA-2021(CEV Stage-IV)/ELTR/2020-2021/548-E01 Dt. 15.03.2022
Noise Report No.	CT0VT 1412 Dt. 13.09.2024

AUTHORISED SIGNATORY		
JAYWANT HARDIKAR HEAD-CMVR	SAURABH DALELA DIRECTOR	Page 2 of 4